

The State of Utah

Department of Natural Resources

Division of Oil, Gas & Mining

ROBERT L. MORGAN Executive Director

LOWELL P. BRAXTON
Division Director

OLENE S. WALKER
Governor

GAYLE F. McKEACHNIE
Lieutenant Governor

Representatives Present During the Inspection:					
Landowner	Seth McCourt Mine Engineer				
OGM	Joe Helfrich Environmental Scientist III				

Inspection Report

Permit Number:	C0150007		
Inspection Type:	COMPLETE		
Inspection Date:	Wednesday, September 15, 2004		
Start Date/Time:	9/15/2004 10:00:00 AM		
End Date/Time:	9/15/2004 3:00:00 PM		
Last Inspection:	Tuesday, August 24, 2004		

Inspector: Joe Helfrich, Environmental Scientist III

Weather: sunny 75

InspectionID Report Number: 404

Accepted by: whedberg

9/22/2004

Permitee: CONSOLIDATION COAL CO

Operator: CONSOLIDATION COAL CO MID-CONTINENT REGION

Site: HIDDEN VALLEY MINE

Address: PO BOX 566, SESSER IL 62884

County: EMERY

Permit Type: PERMANENT COAL PROGRAM

Permit Status: RECLAIMED

Current Acreages		Mineral Ownership	Types of Operations		
960.00	Total Permitted	☐ Federal	✓ Underground		
6.70	Total Disturbed	☐ State	Surface		
6.70	Phase I	☐ County	☐ Loadout		
	Phase II	✓ Fee	Processing		
	Phase III	☐ Other	Reprocessing		

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The purpose of this visit was to conduct a complete inspection of the Hidden Valley reclaimed site. There are no pending amendments, permit conditions, or compliance issues.

Inspector's Signature

Joe Helfrich, Environmental Scientist III

Date

Thursday, September 16, 2004

Inspector ID Number: 1

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Utah!

Permit Number: C0150007 Inspection Type: COMPLETE

Inspection Date: Wednesday, September 15, 2004

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
- a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	\checkmark		\checkmark	
2.	Signs and Markers	V		✓	
3.	Topsoil	V			
— 4.а	Hydrologic Balance: Diversions	~		~	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	V			
4.c	Hydrologic Balance: Other Sediment Control Measures	V		V	
4.d	Hydrologic Balance: Water Monitoring	✓		✓	
4.e	Hydrologic Balance: Effluent Limitations	✓		V	
5.	Explosives		✓		
6.	Disposal of Excess Spoil, Fills, Benches		✓		
7.	Coal Mine Waste, Refuse Piles, Impoundments		✓		
8.	Noncoal Waste		✓		
	Protection of Fish, Wildlife and Related Environmental Issues	✓			
10.	Slides and Other Damage	✓			
11.	Contemporaneous Reclamation		~		
12.	Backfilling And Grading		✓		
13.	Revegetation	✓			
14.	Subsidence Control		✓		
15.	Cessation of Operations		~		
16.8	a Roads: Construction, Maintenance, Surfacing	~			
16.t	o Roads: Drainage Controls	V			
17.	Other Transportation Facilities		~		
18.	Support Facilities, Utility Installations		✓		
19.	AVS Check		✓		
20.	Air Quality Permit		✓		
21.	Bonding and Insurance	✓		✓	
22.	Other		✓		

Permit Number: C0150007 Inspection Type: COMPLETE

Inspection Date: Wednesday, September 15, 2004

Page 3 of 3

1. Permits, Change, Transfer, Renewal, Sale

The reclamation permit was renewed on January 29, 2002 and expires January 30, 2007.

2. Signs and Markers

A sign containing the required information was posted at the entrance to the access road.

4.a Hydrologic Balance: Diversions

There are water bars along the access road that divert runoff to the outslope of the road. At the time of this inspection, they were in good repair and functioning adequately.

4.c Hydrologic Balance: Other Sediment Control Measures

Water was flowing in Ivie Creek at one cfs.

4.d Hydrologic Balance: Water Monitoring

The silt fence on the left side of the reclaimed area is beginning to deteriorate. The MRP requires sampling Ivie Creek above and below the mine in the spring and fall or high and low water 2nd and 3rd quarters. Samples and field measurements were taken on June 8, 2004 for the two sites on Ivie creek. Monitoring at the site is done biannually to capture peak and low flows. This year the runoff peaked in late March. Mr. Behling and I agreed to watch the stream flow and take future samples closer to peak and low flows. Low flow sampling is scheduled for September 21, 2004.

4.e Hydrologic Balance: Effluent Limitations

There are no UPDES outfalls for this site.

21. Bonding and Insurance

The surety bond is on record for \$90,758 and is effective for the permit period. The rider is dated January 8, 1997. Insurance was renewed and is effective from November 5, 2003 to November 5, 2004.